

Im.

# NXCADCAM BackGround Postprocess Application

## **Installation:**

Copy files from the folders to corresponding folders under the NX\_Installation\_folder, for example: C:\Program Files (x86)\Siemens\NX 8.0\UGALLIANCE\Vendor.

### **User Guide:**

**Step 1**: start manufacturing application, and change operation navigator to program order view.

#### **Step 2**:

<Option A>:

NC\_PROGRAM

Select Program from Operation Navigator and then click on the icon



🗦 🛅 Unused Items		
OULT AL_COMZ_D		
OQ ↓ AL_ESQZ_D		
⊘		`
- V 🔄 PROGRAM		50
- 🗸 📴 ALUMINIO		
🖻 🖌 🛅 ACERO		0
🗸 🐫 AL_DE_D		0
AL_PU_D		G
🗸 🦢 AL_PL_D		
<b>√</b>		
✓ ♦ FLOWCUT_SINGLE		
✓ Cartemplado	_	
	7	

NXCADCAM BackC	iroundPost ູ ວ	ο×
Select Post Processor	MILL_3_AXIS	-
Output File name	VP2_FI12	
Output File Folder		
G:\Work\		
🗹 Generate CLS File.		
ОК	Apply Ca	ncel



4

<u>h.</u>

#### <**Option B>:**

No Program group selected from Operation Navigator, click the icon

Name
NC_PROGRAM
🖻 📴 Unused Items
⊘ <b>Ų</b> AL_COMZ_D
⊘ <b>Ų</b> AL_ESQZ_D
ONTOUR_AREA
V C PROGRAM
🗸 🔁 ALUMINIO
🖻 🖌 🔁 ACERO
🗸 🐫 AL_DE_D
<b>√</b> <u>∠</u> <u>AL_PU_D</u>
🗸 🍉 AL_PL_D
<b></b> ✓ 🧐 AL_PL_D_1
✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓
ACERO_TEMPLADO

ヽ NXCADCAM BackGroundPost し 🛛 🕸	<
Program Order View	
Program Groups	
NC_PROGRAM	
PROGRAM	
ALUMINIO ACERO	
ACERO_TEMPLADO	
Operations List	
AL_COMZ_D AL_ESQZ_D	
CONTOUR_AREA	
AL_PU_D	
AL_PL_D AL_PL_D	
FLOWCUT_SINGLE	
Select Post Processor MILL_3_AXIS	
Output File name NC_PROGRAM	
Output File Folder	
G:\Work\	
🧹 Generate CLS File.	
OK Apply Cancel	